













































Parts List

①  x1	②  x2	③  x2	④  x1
⑤  x1	⑥  x1	⑦  x1	⑧  x1
⑨  x1	⑩  x2	⑪  x2	⑫  x1
⑬  x2	⑭  x2	⑮  x2	⑯  x2
⑰  x3	⑱  x3	⑲  x3	⑳  x3
㉑  x3			


Hardware List

A  Ø8x30mm x26	B  x38	C  x38	D  x1
E  x1	F  Ø7x40mm x10	G  M6x12mm x4	H  M6x35mm x4
I  x1	J  Ø4x35mm x14	K  Ø3.5x14mm x26	L  Ø3x16mm x12
M  x12	N  x12	O  x2	P  x2
Q  x8	R  M6x25mm x8	S  Ø3x12mm x36	T  x4
CL  x3	CR  x3	DL  x3	DR  x3


Step 1




Step 2




Step 5




Step 6







Step 7






Step 8





Step 9





Step 10



Step 11




Step 12




x2



Step 13





Step 14





Step 15





Step 16





Step 17





Step 18




Step 19




Step 20






Step 21




Step 22





Step 23




Step 24




Step 25




Step 26




Step 27







Step 28



Step 29




Step 30



x3


Step 31

x3





Step 32

x3






Step 33

x3









Step 34

x3






Step 35

x3





Step 36






x3


Step 37



Step 38



x1




x12

φ3x16mm

x12

Step 39



Step 40

