
























STEP UP
הצעד הראשון לעיצוב הבית




















BY-CT3248




Parts List




①  x1	②  x1	③  x1	④  x1
⑤  x2	⑥  x1	⑦  x1	⑧  x2
⑨  x10	⑩  x2	⑪  x2	⑫  x5
⑬  x5	⑭  x5	⑮  x5	⑯  x5
⑰  x2	⑱  x2	⑲  x4	⑳  x5
㉑  x2			

Hardware List

A  φ8x30mm x53	B  x75	C  x75	D  x1
E  x1	F  φ4x35mm x27	G  φ3x12mm x70	H  φ3x16mm x8
I  φ7x40mm x4	J  M6x30mm x8	K  M6x35mm x20	L  x8
M  x5	N  x24	O  x4	P  φ3.5x18mm x2
Q  x2	R  x2		
DL  x5	DR  x5	CL  x5	CR  x5


Step 1



A  φ8x30mm x10	B  x25	D  x1
---	---	--


x5

Step 2





x5

Step 3




x5

Step 4




x5


Step 5






Step 6




Step 7






G	M	D
		
φ3x12mm x4	x2	x1

x2


Step 8




G	M	D
		
φ3x12mm x4	x2	x1

x2




Step 9






Step 10








Step 11







Step 12




Step 13



Step 14




Step 15




φ8x30mm


x11





x6



x1




Step 16




M6x35mm


x10




x1






Step 17






Step 18




Step 19




Step 20







Step 21







Step 22




Step 23





Step 24




Step 25




Step 26





Step 27



Step 28





Step 29




x4

Step 30




x2




Step 31





Step 32




Step 33




Step 34






Step 35



Step 36



Step 37



Step 38

